

# HIGH PRESSURE SPRAY NOZZLE CHART

Nozzle #	5000 PSI	5300 PSI	5500 PSI	5700 PSI	6000 PSI	6300 PSI	6500 PSI	6700 PSI	7000 PSI	7250 PSI
3.0	3.35	3.45	3.52	3.58	3.67	3.76	3.82	3.88	3.97	4.04
3.5	3.91	4.03	4.10	4.18	4.29	4.39	4.46	4.53	4.63	4.71
4.0	4.47	4.60	4.69	4.77	4.90	5.02	5.10	5.18	5.29	5.39
4.5	5.03	5.18	5.28	5.37	5.51	5.65	5.74	5.82	5.95	6.06
5.0	5.59	5.76	5.86	5.97	6.12	6.27	6.37	6.47	6.61	6.73